


# WIRING DIAGRAM

UZC-3C  
AUXILLARY  
OUTPUT

MODEL 072000  
DIGITAL HUMIDISTAT



- ① EQUIPMENT WIRING NOT SHOWN FOR CLARITY. EQUIPMENT MAY VARY FROM WHAT IS SHOWN
- ② 'M2 COM' JUMPER MUST BE CUT
- ③ DO NOT CUT RH SENSOR JUMPER
- ④ MODEL OAS -- OUTSIDE AIR SENSOR



DRAWING BY: EDK		DWG NAME: MODEL S2000/S2020 -- WIRED w/ UZC-3 & 072000 DIGITAL HUMIDISTAT		DATE: 12/02/04
SIZE: A	REV: A	DWG NO: 090512A0103		
SHEET: 1 OF 1		COPYRIGHT © FIELD CONTROLS INC. ALL RIGHTS RESERVED		

DISCLAIMER: Field Controls Inc. Cannot be held liable for the use or misuse of this supplied information. It is the responsibility of the user to determine the suitability of the application. Malfunctions, improper operation, and/or subsequent damage to any related equipment or property damage as a result of using this supplied information is the responsibility of the user. Field Controls Inc. is not responsible for any misapplications including, but not limited to negligence, defect in products(s), system incompatibility, poor workmanship and/or installation.