



- - - - New wire supplied by installer
- ⊕ Solderless connector (wire nut)

L1 is 120V  
 N is 120V Neutral  
 M is 120V if the motor is running  
 T1 is 120V if there is a call for heat  
 T2 is 120V Neutral  
 T3 is 120V if there is a call for heat

